

		Type	L #	Hits	Search Text	DBs	Time Stamp	Components	Error Definition	Errors
4	BRS	L ₄	5	2 not 3		USPA T; US-P GPUB ; EPO; JPO; DERW ENT	2004/06/1 7 01:21			0
5	BRS	L ₅	85	(1) and (((piezoelectric\$5 or piezo or magnet\$6 or thermal\$3 or pneumatic\$6) near10 (actuat\$4 or pulse\$2 or generat\$5 or element\$1 or driv\$3)) same (piston\$1 or plunger\$2 or rod\$1 or syringe\$1 or barrel\$1))		USPA T; US-P GPUB ; EPO; JPO; DERW ENT	2004/06/1 7 01:23			0
6	BRS	L ₆	0	5 not (3 4)		USPA T; US-P GPUB ; EPO; JPO; DERW ENT	2004/06/1 7 01:24			0

		Type	L #	Hits	Search Text	DBs	Time Stamp	Comments	Error
1	BRS	L 1	1357		(436/49,180).ccls. or (73/864.12,73/864.22).ccls.	USPAT; US-P GPUB ; EPO; JPO; DERW ENT	2004/06/17 01:20		0
2	BRS	L 2	66		((1) and (((piezoelectric\$5 or piezo or magnet\$6 or thermal\$3 or pneumatic\$6) near10 (actuat\$4 or pulse\$2 or generat\$5 or element\$1 or driv\$3)) same (piston\$1 or plunger\$2 or rod\$1 or syringe\$1 or barrel\$1)) and (wash\$3 or rins\$3 or flush\$3)	USPAT; US-P GPUB ; EPO; JPO; DERW ENT	2004/06/17 01:21		0
3	BRS	L 3	156		(422/100.ccls. or 436/180.ccls. or (73/864.13,864.16,86 4.17).ccls.) and (((piezoelectric\$5 or piezo or magnet\$6 or thermal\$3 or pneumatic\$6) near10 (actuat\$4 or pulse\$2 or generat\$5 or element\$1 or driv\$3)) same (piston\$1 or plunger\$2 or rod\$1 or syringe\$1 or barrel\$1))	USPAT; US-P GPUB ; EPO; JPO; DERW ENT	2004/06/17 01:21		0